



Part in Box 1







Part in Box 2









Hardware List

1.	JCBC M6 x 70mm		x 8
2.	M6 x 15mm Barrel Nut		x 8
3.	Wood Dowel M10 x 30mm		x 4
4.	Center Rail Bracket	$[\mathcal{D}_{\circ}\mathbb{Q}]$	x 2

5.	CSK M4 x 16mm	(Dattitt>	x 8
6.	CSK M4 x 25mm	Dammum>	x 26
7.	M4 Allen Key		x 1

Tool required for assembly:

- * Allen Key (supplied)
- * Phillips Screwdriver (not supplied)


ASSEMBLY TIPS


Remove hardware from box and sort by size to check that all hardware and parts are present before assembling. Follow instructions below in the proper sequence to ensure fast, easy and correct assembly.



WARNING!!

DO NOT FULLY TIGHTEN ALL BOLTS UNTIL ALL PARTS ARE IN PLACE. FAILURE TO FOLLOW THIS INSTRUCTION MAY CAUSE THE BOLTS TO BE MISALIGNED DURING THE ASSEMBLY.











(F) Front Panel x 1



(G) Back Panel x 1



(H) Side Panel x 2



(J) Center Support x 1




(K) Drawer Front Panel x 3



(L) Drawer Side Panel x 6



(M) Drawer Back Panel x 3




(N) Drawer Bottom Panel x 3




(0) Drawer Support x 3



Part in Box 4





Hardware List

1.	Caster	40	x 4
2.	CSK M3.5 x 16mm	D ummun	x 22
3.	JCBC M6 x 35mm	<u></u>	x 16
4.	CSK M4 x 25mm	Dannanno-	x 36
5.	Minifix Housing (Short)		x 18
6.	Connecting Bolt	9-1	x 18
7.	M4 Allen Key		x 1

Tool required for assembly:

- * Allen Key (supplied)
- * Phillips Screwdriver (not supplied)


ASSEMBLY TIPS

Remove hardware from box and sort by size to check that all hardware and parts are present before assembling. Follow instructions below in the proper sequence to ensure fast, easy and correct assembly.




WARNING !!

DO NOT FULLY TIGHTEN ALL BOLTS UNTIL ALL PARTS ARE IN PLACE. FAILURE TO FOLLOW THIS INSTRUCTION MAY CAUSE THE BOLTS TO BE MISALIGNED DURING THE ASSEMBLY.







Attached the Center Support (J) onto the Bottom Support Center (I) and Side Panel (H). Tighten the Bottom Support Center (I) and Side Panel (H) to the Front Panel (F) with CSK Screw.

